


RTS Line Voltage Motor Connection Configurations



14/3 ELECTRICAL WIRE RECOMMENDED TO JUNCTION BOX
120 VOLT POWER SOURCE REQUIRED

