


RTS Line Voltage Motor Connection Configurations

— NUTRAL
— HOT
— GROUND



14/3 ELECTRICAL WIRE RECOMMENDED TO JUNCTION BOX
120 VOLT POWER SOURCE REQUIRED

